




FOR MORE INFORMATION
ON THE JB ATLAS WIRELESS
CHARGING SCALE & FULL
MANUAL VISIT US AT
WWW.JBIND.COM

CONNECTING A SMART DEVICE TO WIRELESS SCALE (CONTINUED)

ATLAS


DS-2000S WIRELESS CHARGING SCALE

CONNECT WITH US



6 From the expanding menu, select "Scan" to search for compatible devices

7 Select your scale from the list of detected devices



8 Flashing yellow light indicates that the scale is broadcasting, when connected the light will turn off



QUICK START GUIDE

JB INDUSTRIES

WWW.JBIND.COM 800.323.0811 SALES@JBIND.COM

Form No. DS-2000S-308



JB INDUSTRIES

WWW.JBIND.COM 800.323.0811 SALES@JBIND.COM

HOW TO TURN ON/OFF JB WIRELESS ATLAS SCALE

- 1 Insert 4 AA alkaline batteries into the back of the scale by removing the battery cover screw
- 2 Press and hold the on/off button to turn the scale on. The green light will appear when the unit is on



- 3 Press and hold the on/off button for 1 second to turn the unit off

CONNECTING A SMART DEVICE TO WIRELESS SCALE

REQUIREMENT:

Apple iPhone 4s or higher and iPad 3 or higher

OR

Android 4.3 or higher


INSTALL THE FREE JB DS-20000S APP

Available in the Apple App Store
and Google Play for Android



BEGIN WITH ATLAS OFF AND AN UNPAIRED TABLET OR PHONE

- 1 Check that your smart device is on
- 2 Check that Bluetooth has been enabled in your smart device settings




Bluetooth must be ON to continue

- 3 Turn the scale on by pressing the on/off button



- 4 Open the JB DS-20000S Atlas app on your smart device

- 5 Touch the "JB" icon at the upper left of the app



CONTINUED ON REVERSE SIDE